


8000 / 8100 / WX Time Settings

TEMPERATURE in Centigrade



Note:
 For time settings over 21 seconds:
 - use Power Converter #464-X
 to boost line voltage
 - or use Power Supply #464-B